ScyTek
LaboratoriesMaterial Safety Data Sheet
WSC-MSDSRev. Date: Oct. 18, 2010Revision: 1Page 1 of 2

P.O. Box 3286 - Logan, Utah 84323, U.S.A. - Tel. (800) 729-8350 - Fax (435) 755-0015 - www.scytek.com

Wash Solution Concentrate (50x)

Wash Solution Concentrate (50x)		
WSC		
Laboratory reagent.		
Water, CAS# 7732-18-5		
Polyoxyethylene (23) lauryl ether, CAS# 9002-92-0		
2-methyl-4-isothiazolin-3-one, CAS# 2682-20-4		
5-chloro-2-methyl-4-isothiazolin-3-one, CAS# 26172-55-4		
May contain additional non-hazardous proprietary ingredients.		
Transparent colorless liquid. Odorless.		
Soluble.		
N/A		
Aqueous solution.		
Extinguish fire using water spray, carbon dioxide, chemical foam, or dry chemical.		
Wear personal protection equipment, including a self-contained breathing apparatus		
(S.C.B.A.)		
No unusual fire or explosion hazards expected.		
Stable under normal temporatures and proceures		
Stable under normal temperatures and pressures.		
Strong oxidizing agents, acids, lodine, Chlorine, and Mercury. Carbon monoxide, Carbon dioxide, Sulfur oxides, Hydrogen chloride gase.		
None reported.		
Eye Contact: May cause irritation and redness.		
Skin Contact: May irritate skin.		
Ingestion: May irritate gastrointestinal system.		
Inhalation: May irritate respiratory tract.		
Eye Contact: Unknown.		
Skin Contact: Unknown.		
Ingestion: Unknown.		
Inhalation: Unknown.		
Eye Contact: Immediately flush eyes with copious amounts of water and get immediate		
medical attention.		
Skin Contact: Remove contaminated clothing and wash contact area with mild soap and		
copious amounts of water. Get medical attention if irritation develops.		
Inhalation: Remove person to fresh air. Get medical attention if symptoms worsen.		
Ingestion: Get immediate medical attention.		
HEALTH 1		
HEALTH 1 FLAMMABILITY 0		
FLAMMABILITY 0		
FLAMMABILITY0PHYSICAL HAZARD0		

ScyTek	Material Safety Data Sheet WSC-MSDS		
Laboratories	Rev. Date: Oct. 18, 2010	Revision: 1	Page 2 of 2

P.O. Box 3286 - Logan, Utah 84323, U.S.A. - Tel. (800) 729-8350 - Fax (435) 755-0015 - <u>www.scytek.com</u>

SPILL OR LEAK PROCEDURES:	Wear chemical resistant clothing, gloves, and eye protection. Wear NIOSH/MSHA approved breathing apparatus. Keep material away from heat, flame, ignition sources, and reactive materials. Wipe up or absorb spill using inert absorbent and place in a suitable waste container for disposal.
WASTE DISPOSAL METHOD:	Observe all federal, state and local environmental regulations.
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE:	Wear protective clothing. Avoid contact with skin and eyes. Wash thoroughly after handling. Irritant. Keep container tightly closed. Use in a chemical fume hood. Avoid breathing vapor.
ADDITIONAL COMMENTS:	The above information is believed to be correct but does not purport to be all inclusive and shall be used only as a guide. ScyTek Laboratories shall not be held liable for any damage resulting from handling or from contact with the above product.